IN THE UNITED STATES PATENT AND TRADEMARK OFFICE.

In re patent of: Terry Schwenk

For: Injection Molding Nozzle and Tip Atty. Docket: MMID 2861

Request for Certificate of Correction Under 37 C.F.R. § 1.322

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

It is requested that a Certificate of Correction be issued correcting the following printing errors appearing in the above-identified United States patent. The errors noted are errors made by the Office. Thus, a fee is not required.

Error	Support in the Prosecution History
In column 6, claim 15, line 39, replace	See claim 17 as it appears in Applicant's
"meld" before "bore" with melt	Reply to Notice of Non-Compliant
	Amendment (37 CFR1.121) filed November
	3, 2006.
In column 6, claim 15, line 40, replace	See claim 17 as it appears in Applicant's
"meld" before "bore" with melt	Reply to Notice of Non-Compliant
	Amendment (37 CFR1.121) filed November
	3, 2006
In column 6, claim 18, line 60, after "and"	See claim 21 as it appears in Applicant's
add tip portions	Reply to Notice of Non-Compliant
	Amendment (37 CFR1.121) filed November
	3, 2006.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims as properly allowed, and re-examination is not required.

Patent No. 7,238,019 B2

A copy of Form PTO/SB/44 is attached with the corrections noted.

Respectfully submitted,

MEDLER FERRO PLLC

/Teresa U. Medler/

Teresa U. Medler Attorney for Applicants Registration No. 44,933

Date: July 23, 2007

8607 Rockdale Lane Springfield, VA 22153 (703) 569-8609

Attny Dkt. No.: MMID 2861

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

	Page 1	of 1
PATENT NO. : 7,238,019 B2	, ago	
APPLICATION NO.: 10/810,679		
ISSUE DATE : July 3, 2007		
INVENTOR(S) : Terry Schwenk		
It is certified that an error appears or errors appear in the above-identified patent and t is hereby corrected as shown below:	that said Lette	ers Patent
In column 6, claim 15, line 39, replace "meld" before "bore" with melt		
In column 6, claim 15, line 40, replace "meld" before "bore" with melt		
In column 6, claim 18, line 60, after "and" add tip portions		

MAILING ADDRESS OF SENDER (Please do not use customer number below):
Mold-Masters Limited, 233 Armstrong Avenue, Intellectual Property Dept., Georgetown, Ontario L7G 4X5 CANADA

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to fee (and by the USFTO to process) an application. Confidentially is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is either to issue 1.0 not to complete, including gathering, preparing, and submitting the completed application from to the USFTO. Time will vary depending upon the redvidual cases. Any confidence of the complete of the